



Figure A110a - Bramley Moore: Coping Chainage 525 to 530m



Figure A111a - Bramley Moore: Coping Chainage 530 to 535m

A112 Chainage 535 to 540m



Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
535 to 535.5	Repair	0 to 1.5	-	Concrete repair to brickwork/blockwork
535.5 to 540	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
535.5 to 540	Brickwork / Masonry	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in blocks or limited mortar loss from joints
535 to 540	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
535	Weephole / Outfall	1.5	D = 0.15m	Circular weephole/outfall. Good condition, some degradation but fully operable
535 to 540	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
537	Metalwork	0 (coping)	0.1 x 0.1m	Metal fixing. Good condition, localised surface corrosion

Figure A112 - Bramley Moore: Chainage 535 to 540m

Inspection Date & Time	12th -13th July 2017
Weather Conditions	Warm & Sunny
Water Conditions	Impounded Water
Wall Height (m) [Crest Level / Water Level mOD]	1.8m [+6.6mOD / +4.8mOD]

Features		Present	Features	Present	Features	Present
Anchor			Lock Gate		Recess	
Boat			Manhole		Repair	x
Brickwork / Masonry	x		Marine Growth	x	Sheet Piling	
Chain Post / Fencing			Metalwork	x	Steps	
Cobbles			Miscellaneous		Timber	
Concrete	x		Mooring Bollard		Vegetation	x
Coping	x		Mooring Chain		Weephole / Outfall	x
Fender			Mooring Ring		-	
Hand railing / Fence			Obstruction		-	
Ladder			Opening / Vault		-	

Overall Condition Rating

Overall Assessment	2	Good
--------------------	---	------

Defects

Chainage (m)	Feature	Defect	Level (m from top)	Description
535 to 535.5	Repair	Impact Damage	0 to 0.3	Localised impact damage resulting in chipping/fragmentation of wall materials
535 to 540	Coping	Loss of Mortar	0.4 to 0.5	Mortar loss to coping stone is limited to the surface. Defects are cosmetic only
535 to 540	Brickwork / Masonry	Loss of Mortar	0.5 to 0.8	Mortar loss to bricks/blocks is limited to the surface. Defects are cosmetic only
536	Brickwork / Masonry	Loss of Bricks/Blocks	0.2 to 1.8	Holes in Brickwork / Masonry, likely left by historic fixings. Defects are cosmetic but have the potential to affect the walls integrity.
535 to 537	Concrete	Cracking	0 (coping)	Minor cracking of concrete typical of shrinkage or thermal expansion. Cracks are non-structural




Figure A112a - Bramley Moore: Coping Chainage 535 to 540m



Figure A113a - Bramley Moore: Coping Chainage 540 to 545m



Figure A114a - Bramley Moore: Coping Chainage 545 to 550m



Figure A115a - Bramley Moore: Coping Chainage 550 to 555m



Figure A116a - Bramley Moore: Coping Chainage 555 to 560m



Figure A117a - Bramley Moore: Coping Chainage 560 to 565m



Figure A118a - Bramley Moore: Coping Chainage 565 to 570m

A119 Chainage 570 to 575m



Figure A119 - Bramley Moore: Chainage 570 to 575m

Inspection Date & Time	12th - 13th July 2017
Weather Conditions	Warm & Sunny
Water Conditions	Impounded Water
Wall Height (m)	1.8m (+6.6mOD / +4.8mOD)

Features				
Features	Present	Features	Present	Present
Anchor		Lock Gate		Recess
Boat		Manhole		Repair
Brickwork / Masonry	x	Marine Growth	x	Sheet Piling
Chain Post / Fencing		Metalwork	x	Steps
Cobbles		Miscellaneous		Timber
Concrete	x	Mooring BOLLARD		Vegetation
Coping	x	Mooring Chain		Weephole / Outfall
Fender		Mooring Ring		-
Hand railing / Fence		Obstruction		-
Ladder		Opening / Vault		-

Overall Condition Rating

Overall Assessment	2	Good
--------------------	---	------

Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
570 to 575	Coping	0 to 0.4	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
570 to 575	Brickwork / Masonry	0.4 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in bricks or limited mortar loss from joints
570 to 575	Marine Growth	1.5 to 1.8	-	Minor growth. Features partially obscured
570 to 575	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
570 to 573	Vegetation	0 (coping)	-	Minor growth. Features partially obscured. Vegetation does not affect structural integrity
571	Metalwork	0 (coping)	0.1 x 0.1m	Metal fixing. Good condition, localised surface corrosion

Defects

[illegible]



Figure A119a - Bramley Moore: Coping Chainage 570 to 575m

A photograph showing a stone wall in the foreground, with a red brick building and a body of water in the background. The stone wall is made of large, irregular blocks and has a small, dark, rectangular opening. The red brick building has a white sign with a red circle and a cross. The body of water is dark and calm.

Inspection Date & Time	12th -13th July 2017
Weather Conditions	Warm & Sunny
Water Conditions	Impounded Water
Wall Height (m) [Crest Level / Water Level mOD]	1.8m [+6.6mOD / +4.8mOD]

Overall Condition Rating		
Overall Assessment	2	Good

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
575 to 579	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
575 to 579	Blockwork	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in blocks or limited mortar loss from joints
579 to 580	Repair	0 to 1.5	-	Concrete repair to brickwork/blockwork
575 to 580	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
577.5	Mooring Chain	1.2 to 1.8	-	Fixed within recess. Fair condition, extensive corrosion with minor thickness loss and/or minor damage to links
575 to 580	Vegetation	0 (coping)	-	Minimal growth. Features remain visible. Vegetation does not affect structural integrity
575 to 580	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
579	Metalwork	0 (coping)	0.1 x 0.1m	Metal fixing. Good condition, localised surface corrosion

[illegible]



Figure A120a - Bramley Moore: Coping Chainage 575 to 580m

A121 Chainage 580 to 585m



Figure A121 - Bramley Moore: Chainage 580 to 585m

Inspection Date & Time	12th -13th July 2017
Weather Conditions	Warm & Sunny
Water Conditions	Impounded Water
Wall Height (m) [(Crest Level / Water Level mOD)]	1.8m (+6.6mOD / +4.8mOD)

Features					
Features	Present	Features	Present	Features	Present
Anchor		Lock Gate		Recess	
Boat		Manhole		Repair	x
Brickwork / Masonry	x	Marine Growth	x	Sheet Piling	
Chain Post / Fencing		Metalwork		Steps	
Cobbles		Miscellaneous		Timber	
Concrete	x	Mooring Bollard	x	Vegetation	x
Coping	x	Mooring Chain		Weephole / Outfall	x
Fender		Mooring Ring		-	-
Hand railing / Fence		Obstruction		-	-
Ladder		Opening / Vault		-	-

Overall Condition Rating

Overall Assessment	2	Good
--------------------	---	------

Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
580 to 582	Repair	0 to 1.5	-	Concrete repair to brickwork/blockwork
582 to 585	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
582 to 585	Brickwork / Masonry	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in blocks or limited mortar loss from joints
580 to 585	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
582	Weephole / Outfall	1.5	D = 0.15m	Circular weephole/outfall. Good condition, some degradation but fully operable
580 to 585	Vegetation	0 (coping)	-	Minimal growth. Features remain visible. Vegetation does not affect structural integrity
580 to 585	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
581	Mooring Bollard	0 (coping)	H = 0.4m	Mooring bollard broken, derelict and beyond repair


Defects

Chainage (m)	Feature	Defect	Level (m from top)	Description
582 to 583	Coping	Loss of Mortar	0.3 to 0.5	Mortar loss to coping stone is limited to the surface. Defects are cosmetic only
582 to 583	Brickwork / Masonry	Loss of Mortar	0.5 to 0.8	Mortar loss to bricks/blocks extends below surface and has the potential to weaken/loosen surrounding bricks/blocks
582	Brickwork / Masonry	Loss of Bricks/Blocks	0.2 to 2	Holes in Brickwork / Masonry, likely left by historic fixings. Defects are cosmetic but have the potential to affect the walls integrity.
581	Mooring Bollard	Collapse / Failure	0 (coping)	Mooring bollard has broken in two following impact or overloading. Remains are corroded



Figure A121a - Bramley Moore: Coping Chainage 580 to 585m

A122 Chainage 585 to 590m



Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
585 to 590	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
585 to 590	Brickwork / Masonry	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in bricks or limited mortar loss from joints
585 to 590	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
585 to 590	Vegetation	0 (coping)	-	Minimal growth. Features remain visible. Vegetation does not affect structural integrity
585 to 590	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects

Figure A122 - Bramley Moore: Chainage 585 to 590m

Chainage (m)	Feature	Defect	Level (m from top)	Description
585 to 590	Coping	Loss of Mortar	0.3 to 0.5	Mortar loss to coping stone is limited to the surface. Defects are cosmetic only
589 to 590	Brickwork / Masonry	Loss of Mortar	0.5 to 0.8	Mortar loss to bricks/blocks extends below surface and has the potential to weaken/loosen surrounding bricks/blocks
589 to 590	Brickwork / Masonry	Cracking	0.5 to 1.5	Minor vertical cracking limited to mortar joints indicating potential onset of wall movement/settlement

Defects

Features	Present	Features	Present	Features	Present
Anchor		Lock Gate		Recess	
Boat		Manhole		Repair	
Brickwork / Masonry	x	Marine Growth	x	Sheet Piling	
Chain Post / Fencing		Metalwork		Steps	
Cobbles		Miscellaneous		Timber	
Concrete	x	Mooring Bollard		Vegetation	x
Coping	x	Mooring Chain		Weephole / Outfall	
Fender		Mooring Ring		-	
Hand railing / Fence		Obstruction		-	
Ladder		Opening / Vault		-	

Overall Condition Rating

Overall Assessment	2	Good
--------------------	---	------



Figure A122a - Bramley Moore: Coping Chainage 585 to 590m

A123 Chainage 590 to 595m



Figure A123 - Bramley Moore: Chainage 590 to 595m

Inspection Date & Time	12th - 13th July 2017
Weather Conditions	Warm & Sunny
Water Conditions	Impounded Water
Wall Height (m)	1.8m (+6.6mOD / +4.8mOD)

Features				
Features	Present	Features	Present	Features
Anchor		Lock Gate		Recess
Boat		Manhole	x	Repair
Brickwork / Masonry	x	Marine Growth	x	Sheet Piling
Chain Post / Fencing		Metalwork	x	Steps
Cobbles		Miscellaneous		Timber
Concrete	x	Mooring BOLLARD		Vegetation
Coping	x	Mooring Chain		Weephole / Outfall
Fender		Mooring Ring		-
Hand railing / Fence		Obstruction		-
Ladder		Opening / Vault		-

Overall Condition Rating

Overall Assessment	2	Good
--------------------	---	------

Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
590 to 595	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
590 to 595	Brickwork / Masonry	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in bricks or limited mortar loss from joints
590 to 595	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
590 to 595	Vegetation	0 (coping)	-	Minimal growth. Features remain visible. Vegetation does not affect structural integrity
590 to 595	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
590	Metalwork	0 (coping)	0.1 x 0.1m	Metal fixing. Good condition, localised surface corrosion
594.5	Manhole	0 (coping)	0.5 x 0.5m	Good - Localised surface corrosion with slight loss of thickness. Manhole housing remains sound

Defects

[illegible]



Figure A123a - Bramley Moore: Coping Chainage 590 to 595m

A124 Chainage 595 to 600m



Figure A124 - Bramley Moore: Chainage 595 to 600m

Inspection Date & Time	12th - 13th July 2017
Weather Conditions	Warm & Sunny
Water Conditions	Impounded Water
Wall Height (m)	1.8m (+6.6mOD / +4.8mOD)

Features				
Features	Present	Features	Present	Present
Anchor		Lock Gate		
Boat		Manhole		
Brickwork / Masonry	x	Marine Growth	x	Sheet Piling
Chain Post / Fencing		Metalwork		Steps
Cobbles		Miscellaneous		Timber
Concrete	x	Mooring Bolland	x	Vegetation
Coping	x	Mooring Chain		Weephole / Outfall
Fender		Mooring Ring		
Hand railing / Fence		Obstruction		-
Ladder		Opening / Vault		-

Overall Condition Rating

Overall Assessment	2	Good
--------------------	---	------

Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
595 to 597.5	Repair	0 to 1.5	-	Concrete repair to coping
597.5 to 600	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
597.5 to 600	Brickwork / Masonry	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in blocks or limited mortar loss from joints
595 to 600	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
595	Weephole / Outfall	1.5	D = 0.15m	Circular weephole/outfall. Good condition, some degradation but fully operable
595 to 600	Vegetation	0 (coping)	-	Minimal growth. Features remain visible. Vegetation does not affect structural integrity
595 to 600	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
596	Mooring Bollard	0 (coping)	H = 0.8m	T-Shaped bollard embedded into coping. Good condition, localised surface corrosion

Defects

[illegible]



Figure A124a - Bramley Moore: Coping Chainage 595 to 600m

A125 Chainage 600 to 605m



Figure A125 - Bramley Moore: Chainage 600 to 605m

Inspection Date & Time	12th - 13th July 2017
Weather Conditions	Warm & Sunny
Water Conditions	Impounded Water
Wall Height (m)	1.8m (+6.6mOD / +4.8mOD)

Features				
Features	Present	Features	Present	Present
Anchor		Lock Gate		Recess
Boat		Manhole		Repair
Brickwork / Masonry	x	Marine Growth	x	Sheet Piling
Chain Post / Fencing		Metalwork	x	Steps
Cobbles		Miscellaneous		Timber
Concrete	x	Mooring BOLLARD		Vegetation
Coping	x	Mooring Chain		Weephole / Outfall
Fender		Mooring Ring		-
Hand railing / Fence		Obstruction		-
Ladder		Opening / Vault		-

Overall Condition Rating

Overall Assessment	2	Good
--------------------	---	------

Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
600 to 605	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
600 to 605	Brickwork / Masonry	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in blocks or limited mortar loss from joints
600 to 605	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
600 to 605	Vegetation	0 (coping)	-	Minimal growth. Features remain visible. Vegetation does not affect structural integrity
600 to 605	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
602.5	Metalwork	0 (coping)	0.1 x 0.1m	Metal fixing. Good condition, localised surface corrosion

Defects

[illegible]



Figure A125a - Bramley Moore: Coping Chainage 600 to 605m

A126 Chainage 605 to 610m



Figure A126 - Bramley Moore: Chainage 605 to 610m

Inspection Date & Time	12th - 13th July 2017
Weather Conditions	Warm & Sunny
Water Conditions	Impounded Water
Wall Height (m)	1.8m (+6.6mOD / +4.8mOD)

Features				
Features	Present	Features	Present	Features
Anchor		Lock Gate		Recess
Boat		Manhole		Repair
Brickwork / Masonry	x	Marine Growth	x	Sheet Piling
Chain Post / Fencing		Metalwork	x	Steps
Cobbles		Miscellaneous		Timber
Concrete	x	Mooring BOLLARD		Vegetation
Coping	x	Mooring Chain		Weephole / Outfall
Fender		Mooring Ring		
Hand railing / Fence		Obstruction		-
Ladder		Opening / Vault		-

Overall Condition Rating		
Overall Assessment	2	Good

Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
605 to 610	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
605 to 610	Brickwork / Masonry	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in blocks or limited mortar loss from joints
605 to 610	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
605 to 610	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
606 to 610	Vegetation	0 (coping)	-	Minimal growth. Features remain visible. Vegetation does not affect structural integrity
606	Metalwork	0 (coping)	0.1 x 0.1m	Metal fixing. Good condition, localised surface corrosion

Defects

[illegible]



Figure A126a - Bramley Moore: Coping Chainage 605 to 610m

A127 Chainage 610 to 615m



Features / Condition

Chainage (m)	Feature	Level (m from top)	Dimensions (m)	Description
610 to 612.5	Repair	0 to 1.5	-	Concrete repair to brickwork/blockwork
612.5 to 615	Coping	0 to 0.5	-	Good - Minor cracks created by minor movement. Surface defects in coping or limited mortar loss from joints
612.5 to 615	Brickwork / Masonry	0.5 to 1.8	-	Good - Minor cracks created by minor movement. Surface defects in bricks or limited mortar loss from joints
610 to 615	Marine Growth	1.5 to 1.8	-	Minimal growth. Features remain visible
612.5	Weephole / Outfall	1.5	D = 0.15m	Circular weephole/outfall. Good condition, some degradation but fully operable
610 to 615	Vegetation	0 (coping)	-	Minimal growth. Features remain visible. Vegetation does not affect structural integrity
610 to 615	Concrete	0 (coping)	-	Good - Structurally sound but with minor cracks and localised honeycombing/flaking with no significant defects
611.5	Mooring Bollard	0 (coping)	H = 0.8m	T-Shaped bollard embedded into coping. Good condition, localised surface corrosion

Figure A127 - Bramley Moore: Chainage 610 to 615m

Chainage (m)	Feature	Defect	Level (m from top)	Description
612.5	Brickwork / Masonry	Loss of Bricks/Blocks	0 to 1.8	Holes in blockwork, likely left by historic fixings. Defects are cosmetic but have the potential to affect the walls integrity.
612.5 to 615	Coping	Loss of Mortar	0.3 to 0.5	Mortar loss to coping stone is limited to the surface. Defects are cosmetic only
612.5 to 615	Brickwork / Masonry	Loss of Mortar	0.5 to 1	Mortar loss to bricks/blocks is significant resulting in loosening of bricks/blocks

Defects

Features	Present	Features	Present	Features	Present
Anchor		Lock Gate		Recess	
Boat		Manhole		Repair	x
Brickwork / Masonry	x	Marine Growth	x	Sheet Piling	
Chain Post / Fencing		Metalwork		Steps	
Cobbles		Miscellaneous		Timber	
Concrete	x	Mooring Bollard	x	Vegetation	x
Coping	x	Mooring Chain		Weephole / Outfall	x
Fender		Mooring Ring		-	
Hand railing / Fence		Obstruction		-	
Ladder		Opening / Vault		-	

Overall Condition Rating

Overall Assessment	2	Good
--------------------	---	------