



Plots 08 & 12 • Detail Drawings





Plan Detail

- 01 Original Sash Windows Restored:
 - Remove excess paint from frame and effect repairs if necessary
 - Replace sash cords and service pulleys if necessary
 - Renovate top and bottom sash if necessary, planing off excess paint
 - Prime all exposed woodwork and chalk beading
 - Window restrictors will be necessary (to allow bottom and top sash to slide only 100mm open for safety)
 - New Centre catch lock stainless steel, NOT GOLD!
 - Painted using 2 coats of satin matte white external paint
- Existing stone sills remain unaltered
- 03 Hardwood sill to inside to cover new insulated plasterboard zone, plasterboard bead below to form shadow gap
- Window frame restored and expose
- Existing glass to be replaced with slimline double glazing with the exception of any original Victorian glass panels if any remain. Due to severe vandalism on site, many of the original glass panes are damaged.
- Window frame exposed
- Sash cords and pulleys repaired
- Window reveal sill 12mm painted hardwood
- Plasterboard drylining to return 20mm outside of the existing window architrave- or best dimension to avoid meeting the existing sill- see internal section, bottom corners

Note:


Whilst the windows have arched panes to the top section, the reveal to the inside is rectangular as drawn.

Window Quantities Per Dwelling:

Type 1 (Larger side windows): 1080w x 1575h - 22no. Type 2 (Smaller side & front windows) 910w x 1575h - 14no. Type 3 (Hallway windows) 1440w x 1575h - 2no. Type 4 (Utility Rm window) 800w x 1000h - 1no.

These dimensions are from a survey and measurements must be taken and confirmed by the window manufacturer prior to fabrication. The stated above are approximate only.

> **NEW HALLNo. 04** Next Big Thing Estates 045_03_P020 • No. 04 - Window Detail 1:10 @ A3, 1:5 @ A1 Planning awing. All dimensions are to be checked on site prior to commencing works on site. Any discrepancy found betwe drawing and that given elsewhere or recorded on site shall be notified immediately to the Client architect in writing



- Please refer to window details
- 2 Existing stone sills to remain
- 03 20mm painted hardwood sill to inside, plasterboard bead return under
- 04 Dry-lining to external walls:
 - 70mm insulated plasterboard with vapor barrier
 - Fixed on carrier rails to create a cavity (prevention of damp)
 - All sockets to be recessed, not surface mounted
 - Skim and painted white
 - 150mm square edge skirting (NO TAURUS CURVES)
- O5 Plasterboard returns to window, if possible a thin insulated pb or insulated DPC to be used to reduce cold bridging
- 08 Original (albeit badly damaged and previously crudely infilled) skirting to remain in place
- 7 22mm allowance for both a new oak floor to living areas and carpet to bedrooms
- 08 Original joists & floor boards remain, carpet tiles removed
- RS60 100mm mineral wood insulation friction fitted between joists
- Acoustic hangers screw fixed at 1200 centres (every fourth joist)
- 2 layers of Knauf 'Soundsheild' to create a 60 minute fire barrier Board layout to be staggered, FR beading to perimeter and skimmed. To avoid doubt, no so called 'magic tape' or skimless finished.
- 12 Original architrave (again, badly damaged, chopped and infilled previously) to remain in place with the new ceiling hangers to avoid the perimeter
- 13 Please refer to window details
- 4 Radiators (white convectors)
- All water feeds to be concealed as much as possible to avoid potential burns


NEW HALL No. 04

New Hall • No. 04

Drawing No. Scale 045_03_P022 • Plots 08 & 12 • Ground Floor Section Detail

1:20 @ A3

Planning




- Please refer to window details
- Existing stone sills to remain
- 20mm painted hardwood sill to inside, plasterboard bead return under
- **Dry-lining to external walls:**
 - 70mm insulated plasterboard with vapor barrier
 - Fixed on carrier rails to create a cavity (prevention of damp)
 - All sockets to be recessed, not surface mounted
 - Skim and painted white
 - 150mm square edge skirting (NO TAURUS CURVES)
- Plasterboard returns to window, if possible a thin insulated pb or insulated DPC to be used to reduce cold bridging
- Original (albeit badly damaged and previously crudely infilled) skirting to remain in place
- 22mm allowance for both a new oak floor to living areas and carpet to 07 bedrooms
- New white convector radiators
- Windows restored as per window details
- Any damaged glass repaired.
- No architrave is present within the rooms on first floor however, they are present and made visible in the hallway- see drawing P047
- 12 RS60 100mm mineral wood insulation friction fitted between joists
- Damaged ceilings replaced (water ingress in places)
- New plasterboard, skim and paint finish to ceiling
- All water feeds to be concealed as much as possible to avoid potential burns

NEW HALL No. 04
Client New Hall • No

New Hall • No. 04

045_03_P022 • Plots 08 & 12 • First Floor Section Details

1:20 @ A3 Planning



- 01 Existing Door Repaired, painted anthracite grey- see spec.
- 02 Door surround and frame repaired, painted gloss white as existing
- 03 New slimline double glazing installed, clear glass throughout
- 04 New slimline double glazing installed, clear glass throughout
- 05 New brush steel lettering for door numbers- as per Item 3
- 08 Door arch maintained
- 07 All brickwork maintained
- 08 Timber infill panels repaired and painted gloss white as existing
- 09 New D-Line pull handle brushed stainless steel, as per Item 2
- 10 Digital Lock Access (Item 2):
 - 10A GSD 1 Door Digital Keypad, 50 user (MAS Alarm Systems)
 - Keypad to both sides (no door release to inside)
 - 10B Magnetic Security Lock System GL-1800F 10TB
 - 10C Videx 10 button intercom panel, stainless steel

Note: Magnetic lock to be connected to Fire Alarm System so the lock releases when fire alarm sounds

- 11 New brushed stainless steel locks with thumb turns items 5 & 6
- 12 Protective brushed stainless steel kick-plate as per item 4
- 13 Existing access ramp and handrails remain handrails painted black





Item 1

Item 2





Item 3

Item 4






lt**eten5**5

It**etrans** 6

NEW HALL No. 04
Client Next Big Thing Next Big Thing Estates 045_03_P023 • Front Door Details

1:20 @ A3

Design Development



- 01 Bathroom & Laundry Room to other side
- 02 Door removed and kept to allow for access to rooms
- 03 Walls patch repaired and painted
- 04 Architrave patch repaired and painted
- 05 Skirting boards patch repaired and painted
- 08 Door frames unaltered and painted
- 07 Wall mounted emergency rated lights Item 3 (60 minute battery)
- 08 Skirting boards patch repaired and painted
- 09 Outline of existing stair no alterations required
- 10 All switches and keypads mounted centre to lights and doors
- 11 Front door maintained and repaired as per details on P046
- 12 Doors maintained if possible, new ironmongery used- items 1 & 2
- 13 New mat utilising existing mat-well
- 14 New timber floor to replace existing carpet tiles
- 15 Zumtobel square emergency light, centre over door item 4










NEW HALL No. 04

Client Next Big Thing Estates

Orawing 045_03_P024 • Ground Floor Hallway Details

1:20 @ A3



- 01 Windows restored please refer to drawing P44
- 02 Low surface temperature radiators
- 03 Apartment Entrance
- 04 Fan Light remains, painted panel in front with 20mm offset to all edges
- 05 Door opening remain, painted panel infill with 20mm offset to all edges
- 08 Skirting boards remain, paint finish
- 07 Emergency lights as per item 01-60 min battery needed
- 08 Fan light frame remains
- 09 Door frame remains
- 10 Architrave remains, ceiling to be patch repaired and painted.
- 11 Walls to be made good (patch repair) and painted.
- 12 Timber floor to replace carpet tiles


Item 2: Zumtobel square illuminated emergency exit lights where required





NEW HALL No. 04
Client Next Big Thing Next Big Thing Estates

045_03_P025 • First Floor Hallway Details 1:20 @ A3




lotes:

This new wall is a client requirement to prevent occupant's self harm, or worse, by climbing over the existing balustrade. The existing balustrade will be maintained with a new 120mm stud wall built around it, using the return angle for stability.

		, .				
N	EW	HA	LL	No.	04	

NEW HALL	NO. U4
Client	Next Big Thing Estates
Drawing	045_03_P026 • Hallway: New Stair Wall
Seale	1:25 @ A3
Status	Design Development




Notes:


This new wall is a client requirement to prevent occupant's self harm, or worse, by climbing over the existing balustrade. The existing balustrade will be maintained with a new 120mm stud wall built around it, using the return angle for stability.

Ν	EW	$^{\prime}$ H	ΑL	LN	0.	04

Client	Next Big Thing Estates
Drawing No.	045_03_P027 • Plots 08 & 12 • Hallway Stair Wall

1:25 @ A3 Planning





Ground Floor

Window No.	Replacement	Proposed Restoration Works	Window Surrounds Present	Dry Lining Detail
W01	No	As per drawing 045 03 P020	Yes	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
W02	No	As per drawing 045 03 P020	Yes	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
V03	No	As per drawing 045_03_P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V04	No	As per drawing 045 03 P020	Yes	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
V05	No	As per drawing 045 03 P020	No	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
V08	No	As per drawing 045 03 P020	No	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
V07	No	As per drawing 045 03 P020	No	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
V08	No	As per drawing 045 03 P020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V09	No	As per drawing 045_03_P020	Yes	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
/10	No	As per drawing 045 03 P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/10a	No	As per drawing 045 03 P020	Yes	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
V10b	No	As per drawing 045_03_P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V11	No	As per drawing 045_03_P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V12	No	As per drawing 045 03 P020	Yes	As per drawing 045 03 P020 (Original Window Surrounds Left On Show)
/13	No	As per drawing 045_03_1 020	Yes	As per drawing 045_03_1 020 (Original Window Surrounds Left On Show) As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V13 V14	No	As per drawing 045_03_1 020 As per drawing 045_03_1 020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/15	No	As per drawing 045_03_1 020 As per drawing 045_03_1 020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show) As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/16	No	As per drawing 045_03_1 020	Yes	As per drawing 045_03_F020 (Original Window Surrounds Left On Show)
/17	No	As per drawing 045_03_1 020 As per drawing 045_03_1 020	Yes	As per drawing 045_05_1 020 (Original Window Surrounds Left On Show) As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/18	No	As per drawing 045_03_1 020 As per drawing 045_03_1 020	Yes	As per drawing 045_05_1 020 (Original Window Surrounds Left On Show) As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V19	No	As per drawing 045_03_1 020 As per drawing 045_03_1 020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show) As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V20	No	As per drawing 045_03_1 020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show) As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V20 V22	No	As per drawing 045_03_1 020 As per drawing 045_03_1 020	Yes	
/22 /22	No	As per drawing 045_03_F020 As per drawing 045_03_F020	No Tes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show) As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
v22 V23	No	As per drawing 045_03_F020 As per drawing 045_03_F020	No	
/23 /24	No	As per drawing 045_03_F020 As per drawing 045_03_F020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/25	No	·	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
v25 V26	No	As per drawing 045_03_P020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/20 /27	No	As per drawing 045_03_P020	-	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
	No	As per drawing 045_03_P020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/28 /29	No	As per drawing 045_03_P020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
	No	As per drawing 045_03_P020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/30 /31	No	As per drawing 045_03_P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
		As per drawing 045_03_P020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/32	No	As per drawing 045_03_P020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/33	No	As per drawing 045_03_P020	No	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V34	No	As per drawing 045_03_P020	No Yan	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
/35	No	As per drawing 045_03_P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V36	No	As per drawing 045_03_P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
V37	No	As per drawing 045_03_P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)
N38	l No	As per drawing 045_03_P020	Yes	As per drawing 045_03_P020 (Original Window Surrounds Left On Show)

Door No.	Replacement	Proposed Works		
D01	No	As per drawing 045_03_P023 (original door restored, glass pane restored)		
D02	No	Original Door- To be Maintained		
D03	No	Original Door- To be Maintained		
D04	No	Original Door- To be Maintained		
D05	Yes	Not original fire door- glass infill present		
D05a	Yes	Not original fire door- glass infill present		
D08	Yes	Not original fire door- glass infill present		
D07	Yes	Not original fire door- glass infill present		
D08	Yes	Not original fire door- glass infill present		
D09	Yes	Not original fire door- glass infill present		
D10	Yes	Not original fire door- glass infill present		
D11	Yes	Not original fire door- glass infill present		
D12	Yes	Not original fire door- glass infill present		
D12a	Yes	Not original fire door- glass infill present		
D13	No	Original door restored, painted gloss black		
D13a	No	Original door restored, painted gloss black		
D14	No	Original Door- To be Maintained		
D15	No	Original Door- To be Maintained		
D16	Yes	Not original fire door- glass infill present		
D17	Yes	Not original fire door- glass infill present		
D18	Yes	Not original fire door- glass infill present		
D19	Yes	Not original fire door- glass infill present		
D20	Yes	Not original fire door- glass infill present		
D21	Yes	Not original fire door- glass infill present		
D22	Yes	Not original fire door- glass infill present		
D23	No	Original Door- To be Maintained		
D24	Yes	Not original fire door- glass infill present		
D25	No	Original Door- To be Maintained		
D26	Yes	Not original fire door- glass infill present		

Note:


All original radiators were previously removed by LCC and replaced by LST covered radiators and standard convector radiator panels, all served with new thinner copper pipe feeds.


There are a few original sinks (removed and relocated by LCC and listed on the photo sheets on this application) and one original 'Belfast Sink' (also relocated by LCC) which will be removed and securly fixed & stored on the Newhall site, within the outbuildings behindPlot 21


Plot 21 outbuildings are referred to in the previously granted application number 14L/1091 & 14F/1089, issued on 04/ 08/ 14.

- Remaining doors shown on the plan are toilet cubical door swings and are recent additions.
- To avoid doubt, all existing doors will be re-used within this building

NEW HAL	LNo. 04
Client	Next Big Thing Estates
Drawing No.	045_03_P028 • Plot 28 • Window & Door Schedule
Scale	Not to Scale
Status	Planning
	I dimensions are to be checked on site prior to commencing works on site. Any discrepancy found between and that given elsewhere or recorded on site shall be notified immediately to the Client architect in writing.








Client
Next Big Thing Estates

Drawing No.

Scale
1:10 @ A3

Status
Planning
Do not scale from his drawing All dimensions are to be checked on site prior to commencing works on site Any, discrepancy found here





Type 1 is is relevant to all the doors with fanlights where they are maintained on the door schedule. The exception to this is: Note:


- D14 The door & fanlight remain but the fanlight restictor is removed- see type 2 D15 The door & fanlight remain but the fanlight restictor is removed- see type 2 D16 The door is not required due to the proposed layouts and will be stored and fixed

Note: Type 2 is when the doors must be fixed shut with acoustic separation behind it. The doors will not be damaged or have any studwork fixed to them, just shut and locked. We also need to do this for the necessary fire compartmentation to the apartments.

NEW HAL	LNo. 04
Client	Next Big Thing Estates
Drawing No.	045_03_P030 • Fan Light Detail
Scale	1:10 @ A3
Status	Planning
	All dimensions are to be checked on site prior to commencing works on site. Any discrepancy found between g and that given elsewhere or recorded on site shall be notified immediately to the Client architect in writing.







NEW HALL No. 04
Client Next Big Thing Next Big Thing Estates 045_03_P035 • Kitchen Details 1:25 @ A3 Design Development