


012345 10



GENERAL NOTES


External brickwork to be treated for dry rot Internal floors - carefully remove existing floor boards where required to replace and treat rotten joists for dry and wet rot. New boards to match existing width and material. Timber to be exposed and finish to be even and uniform. Tiled floors to staircase areas to be retained and refurbished and protective coating to leave exposed as finish.


Wall & Ceiling plaster finish to be skimmed to match existing with feature plaster details damaged or missing to be matched and replaced where necessary by specialists. Timber stud walls that need to be removed carefully leaving a 200mm downstand to show the original room proportions and features including plaster cornices and roses to be reinstated to match existing.

Fireplaces to be retained, refurbished and made good with flue for use.

All patching of timber skirting, architraves to match existing.

New openings to height that matches existing doorways to maximum 2400mm





2. Do not scal	g is copyright of L7 architects le from this drawing I dimensions only				
rev. date				d	rn aud
PRC PRC	POSED_GROUND_	FLOC	DR_	_PL	AN
2a Myrtle Str Liverpool L7 7DP 0151 708 515 office@L7arc www.L7archi	be L7 al	rchit	teo	cts	5
Liverpool L7 7DP 0151 708 515 office@L7arc	be L7 al	Scale	Drawn	Checked	Date
Liverpool L7 7DP 0151 708 515 office@L7arc www.L7archi	59 shitects.co.uk tects.co.uk			Checked	