

Contract:				Client:			Trial Pit:			
Project E	3lue				E	Buro Happold			Р	102
Contract Ref:	Start:	12.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	12.12.17		6.62		E:333534.9 N:392557.1		2	of	4

Pit facing north





Method Used: Machine dug Plant Used:

Mini tracked excavator

Logged

Checked Ву: **GGoldthorpe**

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 16:22 | AJ4 |

Eastern face



Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			Р	102
Contract Ref:	Start:	12.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	12.12.17		6.62		E:333534.9 N:392557.1		3	of	4

Western face





Northern face of pit

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 16:22 | AJ4 |

Method Used: **Machine dug**

Plant Used:

ed: Mini tracked excavator

Logged By:

GGoldthorpe By:

Checked By:

PMR





Contract:				Client:		Trial Pit:			
Project E	Blue				Buro Happold			Р	102
Contract Ref:	Start:	12.12.17	Groun	d Level (m):	National Grid Co-ordinate:	Sheet:			
764393	End:	12.12.17		6.62	E:333534.9 N:392557.1		4	of	4

Wooden boards on northern side of pit





Spoil

Method
Used: Machine dug

Plant Used:


sed: Mini tracked excavator

Logged By: GGoldthorpe Checked By:

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 16:23 | AJ4 |






TRIAL PIT LOG

Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold		ı	P1(02.1
Contract Ref:	Start:	13.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	13.12.17		6.62		E:333532.6 N:392556.9		1	of	4

Į		•		Liid.					•
	Samp	oles a	nd In-si	tu Tests	Water	Backfill	Description of Strate	Depth	Material Graphic
	Depth	No	Туре	Results	Wa	Вас	Description of Strata	(Thick ness)	Legend
	0.00-0.50	1	В				MADE GROUND: Loose yellow fine to coarse SAND (Stockpile sand)	0.05	
	-						MADE GROUND: Rectangular granite 'bricks' average 0.20 x 0.10m	0.25	
AJ4		400	50				\in size // MADE GROUND: Red brick wall (0.60m width) Western side of the wall exposed is a water filled 'void'/channel depth 1.10m. In central	(0.45)	
- 16:23	0.50	102	ES PID	1.2ppm			part of pit wall recovered as orange not brown sandy very coarse gravel of red bricks, some concrete and tarmacadam. Sand is coarse \(\cap of ash and weathered sandstone.\)	0.70	
Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, 31/05/18 - 16:23 AJ4	0.70 - 0.70 -	103	ES PID	1.5ppm			MADE GROUND: Wooden board over 'void'/channel. Inaccessable for sampling.	-(0.40)	
o.uk.	_							1.10	
soils.c	-						Trial pit terminated at 1.10m depth.	_	
ask@	-							_	
Email:	-							-	
o.uk, l	-							_	
soils.c	-							-	
. www	-							_	
, Web	-							-	
52299	-							_	
977-5	-							-	
ax: 01	-							-	
255, F	- -							-	
77-552	-							-	
I: 019	-							-	
NJ. Te	-							-	
F10 1	-								
ire, W	-							-	
Yorksh	-							_	
West	-							-	
eford,	-							_	
Castle	-							_	
Street,	-							-	
ottery \$	-							-	
teries, Pottery Street, Castleford, West	-							-	
ا ۋ									





Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold		ı	P10)2. 1
Contract Ref:	Start:	13.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	13.12.17		6.62		E:333532.6 N:392556.9		2	of	4

Pit facing north





Western face

Method Used: Machine dug Plant

Logged

Ву:

Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 16:23 | AJ4 |

Used:

Mini tracked excavator

GGoldthorpe



Contract:				Client:			Trial Pit:				
Project E	Blue				E	Buro Happold		ı	P10)2 .	1
Contract Ref:	Start:	13.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	13.12.17		6.62		E:333532.6 N:392556.9		3	of	4	ŀ

Western face





Southern face

Method Used:

Machine dug

Plant Used:

Mini tracked excavator

Logged

GGoldthorpe

Checked Ву:

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk. | 31/05/18 - 16:24 | AJ4 |



Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			P10	2.1
Contract Ref:	Start:	13.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	13.12.17		6.62		E:333532.6 N:392556.9		4	of	4

Wooden boards and void in northern side of excavation





Void on western face

Method Used:

Machine dug

Plant Used:

Logged

Checked




GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk. | 31/05/18 - 16:24 | AJ4 |

Mini tracked excavator

GGoldthorpe

PMR






TRIAL PIT LOG

Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			Р	105
Contract Ref:	Start:	11.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	11.12.17		6.65		E:333289.2 N:392474.4		1	of	4

	Samı	oles a		tu Tests	<u></u>			Depth	Material
	Depth	No	Туре	Results	Water	Backfill	Description of Strata	(Thick ness)	Graphic Legend
	0.00-0.05	1	В				MADE GROUND: Tarmacadam with coarse gravel size rounded clasts of mixed lithologies. MADE GROUND: Granite stone 0.10 x 0.10m in size. MADE GROUND: Non reinforced CONCRETE with coarse gravel of [0.05	
31/05/18 - 16:24 AJ4	0.50 - 0.50 - 0.50-1.00 - 0.50	103 2 4	ES B B PID	0.7ppm			cobble sized clasts of mixed lithologies over granite 'stones' (0.40 x 0.20 x 0.20m). MADE GROUND: Non reinforced CONCRETE coarse gravel to cobble sized clasts of mixed lithologies. MADE GROUND: Orangish reddish brown fine to coarse SAND and GRAVEL of sandstone. Sand is fine to coarse. Sandstone is subrounded low cobble content.	0.50	
il: ask@soils.co.uk.	1.00 - 1.00-2.00 - 1.00	105 6	ES B PID	0.1ppm				- - -	
ww.soils.co.uk, Ema	- 1.50 - 1.50 - -	107	ES PID	0.1ppm				- (2.20) - -	
1977-552299, Web: v	2.00 - 2.00-2.70 - 2.00	108 9	ES B PID	0.1ppm				- - -	
552255, Fax: 0	2.50 - 2.50	110	ES PID	0.1ppm			Trial pit terminated at 2.70m depth.	2.70	
leries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk. 31/05/18 - 16:24 AJ4								- - - - - - - - - - -	



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 1008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, | 31/05/18 - 16:24 | AJ4 |



Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			P	105
Contract Ref:	Start:	11.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	11.12.17		6.65		E:333289.2 N:392474.4		2	of	4

Southern face





Northern face

Used: Machine dug

Plant Used:

Logged

Checked Ву:

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk. | 31/05/18 - 16:25 | AJ4 |

Method

Mini tracked excavator

GGoldthorpe



Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			Р	105
Contract Ref:	Start:	11.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	11.12.17		6.65		E:333289.2 N:392474.4		3	of	4

Western face





Eastern face

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 16:25 | AJ4 | Method Used:

Machine dug

Plant Used:

Mini tracked excavator

Logged

Ву: **GGoldthorpe**

PMR



Checked




TRIAL PIT LOG

Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			Р	105
Contract Ref:	Start:	11.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	11.12.17		6.65		E:333289.2 N:392474.4		4	of	4

Spoil





Method Used:

Machine dug


Plant Used:

nt ^{ed:} **Mini tracked excavator** Logged Bv

GGoldthorpe Checked By:

PMR








TRIAL PIT LOG

Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			Р	106
Contract Ref:	Start:	15.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	15.12.17		6.67		E:333285.9 N:392521.7		1	of	3

	Jies a	11u 111-51	tu Tests	(1)	7=			Material
Depth	No	Туре	Results	Water	Backfill	Description of Strata	Depth (Thick ness)	Graphic Legend
						MADE GROUND: TARMACADAM with coarse subrounded gravel of mixed lithologies. MADE GROUND: Extremely weak reinforced CONCRETE with rounded coarse gravel to cobble sized clasts of mixed lithologies.		
0.50-1.00 0.50 0.50	1 101	B ES PID	0.0ppm			0.55m - 1.25, on eastern part of face 1 a brick wall cobbles. Wall is 0.20m wide comprising 2 thickness red brick. Eastern wall of pit concrete wall, appearing to have been cast into wood. MADE GROUND: Orangish reddish brown sandy coarse subrounded	0.60	
1.00 1.00-2.00 1.00	102 2	ES B PID	0.1ppm			to subangular GRAVEL and cobbles sized areas.	- - -	
1.50 1.50	103	ES PID	0.2ppm					
2.00 2.00	104	ES PID	0.1ppm				- - -	
2.50 2.50	105	ES PID	0.1ppm	1			-	
-						Trial pit terminated at 3.10m depth.	3.10	
	0.50 0.50 1.00 1.00-2.00 1.00 1.50 1.50 2.00 2.00	0.50	0.50	0.50	0.50 101 ES O.0ppm 1.00 102 ES O.0ppm 1.00-2.00 2 ES O.1ppm 1.50 103 ES O.2ppm 1.50 104 ES O.1ppm 2.00 104 ES O.1ppm 2.50 105 ES PID O.1ppm	0.50	0.50-1.00 0.50 0.50 0.50 0.50 0.50 0.50 0.50	0.50-1.00



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 1008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, | 31/05/18 - 16:25 | AJ4 |



Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			Р	106
Contract Ref:	Start:	15.12.17	Grour	nd Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	15.12.17		6.67		E:333285.9 N:392521.7		2	of	3

Northern face





Southern face

Method Used: **Machine dug**

Plant Used:

sed: Mini tracked excavator

Logged By:

GGoldthorpe

Checked By:

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, | 31/05/18 - 16:26 | AJ4 |



Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold			Р	106
Contract Ref:	Start:	15.12.17	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	15.12.17		6.67		E:333285.9 N:392521.7		3	of	3

Eastern face





Western face

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 16:26 | AJ4 | Method Used:

Machine dug

Plant Used:

Mini tracked excavator


Logged

GGoldthorpe

Checked Ву:

PMR








Contract:			Client:		Trial Pit	:		
Proje	ct Blue			Buro Happold		Т	PSS	31.1
Contract Ref:	Start:	08.01.18	Ground Level (m):	National Grid Co-ordinate:	Sheet:			
764393	End:	08.01.18	6.56	E:333393.0 N:392568.2		1	of	4

	Samp	les a	ınd In-si	tu Tests	ter	₩	D 18 10 1	Depth	Material
	Depth	No	Туре	Results	Water	Backfill	Description of Strata	(Thick ness)	Graphic Legend
teries, Potary Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, 31/05/18 - 15:05 AJ4					1		MADE GROUND: Dark brown to black (orangish yellow on a fresh surface) rectangular sandstone blocks (cobbles) (average 30cm x 10cm x 15cm). In northern part of excavation 'stepped' brickwork wall at 3 levels: Ground level-0.80m; 0.80-1.25m and 1.25m to bottom of pit. MADE GROUND: Orangish reddish brown slightly clayey SAND and GRAVEL. Gravel is subrounded coarse of sandstone. Medium cobble content also of coarse sandstone. Very strong odour of 'tar' and coarse gravel to cobble size pieces of bitumen excavated in the northern part of the excavation. Trial pit terminated at 2.20m depth.	- 0.15	




GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 1008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, | 31/05/18 - 15:05 | AJ4 |



Contract:				Client:			Trial Pit:	-		
Project E	Blue				E	Buro Happold		TF	PSS	31.1
Contract Ref:	Start:	08.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	08.01.18		6.56		E:333393.0 N:392568.2		2	of	4

Whole pit looking northward





Eastern face

Method Used:

Machine dug

Logged

Checked **GGoldthorpe**

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:05 | AJ4 |

Plant Used:


13 Ton Tracked Excavator



Contract:				Client:			Trial Pit:				
Project E	Blue				E	Buro Happold		TF	25	31.	1
Contract Ref:	Start:	08.01.18	Grour	nd Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	08.01.18		6.56		E:333393.0 N:392568.2		3	of	4	

Western face





Pit facing southward

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:06 | AJ4 |

Method Used:

Machine dug

Plant Used:

ed: 13 Ton Tracked Excavator

Logged By: GGoldthorpe Checked By:

ed PMR





Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold		TF	PSS	31.1
Contract Ref:	Start:	08.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	08.01.18		6.56		E:333393.0 N:392568.2		4	of	4

Close up of brickwork in northern end of pit





Spoil

Method Used:

Machine dug

Plant Used:

Logged

GGoldthorpe


Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:06 | AJ4 |

13 Ton Tracked Excavator






STRUCTURAL SOILS

TRIAL PIT LOG

Depth Material

Contract:				Clie	ent:			Trial P	it:		
Project E	Blue					- 1	Buro Happold		TP	SS	1.2
Contract Ref:	Start:	09.0	1.18	Ground Le	evel (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	09.0	1.18	(6.57		E:333406.0 N:392568.3		1	of	4
Samples and In-situ Tests	;	ē	■						Depth	Ма	ıteria

Samples a	1114 111-51	ESIS	Wate	Backfil	Description of Strata	(Thick	
Depth No	Туре	Results	Š	Ва	Besonption of office	ness)	Legend
					MADE GROUND: Black (yellow on fresh surface) rectangular blocks (cobbles) of sandstone (30cm x 10cm x 15cm) In northern part of excavation brickwork structure present from ground level to the bottom of the pit; wall on two levels: ground level-0.90m and 0.90 to bottom of pit. MADE GROUND: Black fine to coarse subrounded to rounded SAND and GRAVEL with angular fine to coarse gravel sized bitumen. Very strong smell of 'tar' and hydrocarbon at 0.50m, large sandstone block 0.70m x 0.70m.	0.15	
1.50 101	ES		+		MADE GROUND: Orangish reddish brown subangular fine to coarse GRAVEL and SAND. Gravel of sandstone.	-(1.20)	
			<u></u>		Water ingress at 2.00m: strongly discoloured with strong hydrocarbon odour. Trial pit terminated at 2.00m depth.	2.00	
						- - - - - -	



GINT_LIBRARY V8 06.GLB LibVersion: v8_06_018 PrjVersion: v8_06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8_06. Structural Solis Ltd, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soli



Contract:	Project Blue			Client:			Trial Pit:	Trial Pit: TPSS1			
Project E	Blue				E	Buro Happold		TF	PSS	1.2	
Contract Ref:	Start:	09.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	09.01.18		6.57		E:333406.0 N:392568.3		2	of	4	

Pit looking northward





Southern face

Method Used:

Machine dug

Plant Used:

13 Ton Tracked Excavator

Logged

GGoldthorpe

Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:07 | AJ4 |



Contract:				Client:							
Project E	Blue				E	Buro Happold		TF	PSS	31.2	
Contract Ref:	Start:	09.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	09.01.18		6.57		E:333406.0 N:392568.3		3	of	4	

Eastern face





Western face

Method Used:

Machine dug

Plant Used:

Jsed: 13 Ton Tracked Excavator

Logged By:

GGoldthorpe Check By:

Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:07 | AJ4 |



Contract:			Client:	lient:						
Project E				E	Buro Happold		TF	25	S1.2	
Contract Ref:	Start:	09.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	09.01.18		6.57		E:333406.0 N:392568.3		4	of	4

Brickwork in northern part of pit





Spoil

Method Used:

Machine dug

1

Plant Used:

13 Ton Tracked Excavator


Logged By:

GGoldthorpe

Checked By: PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:08 | AJ4 |






TRIAL PIT LOG

Contract:				Client:			Trial Pit:				
Project E	Blue				Е	Buro Happold		TF	25	S1.	3
Contract Ref:	Start:	10.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	10.01.18		6.58		E:333396.4 N:392554.7		1	of	4	

Sam Depth	ples a		tu Tests Results	Water	Backfill	Description of Strata	Depth (Thick ness)	Materia Graphi Legen
1.50	101	ES		1		MADE GROUND: Reinforced CONCRETE with angular sub to subrounded fine to medium gravel sized clasts of mixed lithologies. MADE GROUND: Reddish orange brown clayey SAND and GRAVEL. Gravel is subrounded to subangular fine to coarse of sandstone. Sand is fine to coarse. Some fine to coarse fragments of bitumen, up to large cobble size. Faint hydrocarbon 'tar' odour. Trial pit terminated at 2.20m depth.	(0.90)	
Plan (Not to	Plan (Not to Scale)					General Remarks		
Bearing -	4	4.2	0 → 348°	2. \ 3. I 4. (Water s Excavat	scanned with GPR, CAT and Genny prior to excavation. eepage at 2.00m. tion unstable on all sides, frequent collapses. pletion, borehole backfilled with arisings.		
Mother			DI			All dimensions in metres Scale: 1:25		
Method Used:	Mad	chine c	Plar Use		3 Ton	Tracked Excavator Logged Checked By: GGoldthorpe By: Property Checked Checked Checked By: Property Checked Che	MR	AC






Contract:				Client:			Trial Pit:	Pit:			
Project E	Blue				E	Buro Happold		TF	255	31.3	
Contract Ref:	Start:	10.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	10.01.18		6.58		E:333396.4 N:392554.7		2	of	4	

Northern face





Southern face

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:08 | AJ4 | Method Used:

^{od} ^{I:} Machine dug Plant Used:

sed: 13 Ton Tracked Excavator

Logged By:

GGoldthorpe Check By:

Checked By:

PMR A

AGS



Contract:			Client:	Client:							
Project E	Blue				E	Buro Happold		TF	25	31 .	3
Contract Ref:	Start:	10.01.18	Ground	d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	10.01.18		6.58		E:333396.4 N:392554.7		3	of	4	

Western face





Eastern face

Method Used:

Machine dug

Used:

Logged

GGoldthorpe

Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:09 | AJ4 |

Plant

13 Ton Tracked Excavator



Contract:	Contract: C						Trial Pit:			
Project E	Blue				В	uro Happold		TF	PSS	31.3
Contract Ref:	Start:	10.01.18	Groun	d Level (m):	1	National Grid Co-ordinate:	Sheet:			
764393	End:	10.01.18		6.58		E:333396.4 N:392554.7		4	of	4

Spoil






Method Used:

13 Ton Tracked Excavator

Checked

PMR








TRIAL PIT LOG

Contract:				Client:			Trial Pit:			
Project E	3lue				I	Buro Happold		TI	PSS	31.4
Contract Ref:	Start:	12.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	12.01.18		6.54		E:333387.4 N:392559.5		1	of	4

Samp Depth	les a	nd In-si Type	tu Tests Results	Water	Backfill	Description of Strata	Depth (Thick	Material Graphic
0.00-1.50	101	ES	Results	>	<u> </u>	MADE GROUND: Greyish yellow rectangular to square sandstone blocks (0.10m x 0.10m x 0.15m).	ness) - 0.15	Legend
						MADE GROUND: On western face brick work is present to 1.00m depth with southern faces having hard angular shiny black bitumen present to 0.30m. Metaliic piping/cabling found and excavatd at 0.30m. A concrete block also in centre of pit; dimensions visible 0.70m x 1.00m.	- - - (0.85)	
				<u>‡</u>		MADE GROUND: Orangish reddish brown fine to coarse SAND and GRAVEL. Gravel is subrounded of sandstone. Some course angular gravel of bitumen. Trial pit terminated at 2.25m depth.	1.00	
							-	



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PriVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk. | 31/05/18 - 15:09 | AJ4 |