

Contract:			Client:	Trial Pit:						
Project E	Blue				E	Buro Happold		TF	25	31.4
Contract Ref:	Start:	12.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	12.01.18		6.54		E:333387.4 N:392559.5		2	of	4

Eastern face





North and west faces

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:09 | AJ4 |

Method Used:

Machine dug

Plant Used:

Jsed: 13 Ton Tracked Excavator

Logged By:

GGoldthorpe

Checked By:





Contract:				Client:	Trial Pit:					
Project E				E	Buro Happold		TF	PSS	31.4	
Contract Ref:	Start:	12.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	12.01.18		6.54		E:333387.4 N:392559.5		3	of	4

North eastern corner of pit





Spoil

Method Used:

Machine dug

Plant

Logged

Checked Ву:

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:09 | AJ4 |

Used:

13 Ton Tracked Excavator

GGoldthorpe



Contract:				Client:	Client:							
Project E	Project Blue					Buro Happold		TF	PSS	1.4		
Contract Ref:	Start:	12.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:					
764393	End:	12.01.18		6.54		E:333387.4 N:392559.5		4	of	4		

Metallic piping from spoil



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:10 | AJ4 |

Method Used:

Machine dug

Plant Used:


13 Ton Tracked Excavator

Logged

GGoldthorpe

Checked By:








TRIAL PIT LOG

-										
Contract:					Client:		Trial Pi	it:		
Project E	Blue					Buro Happold		TP	SS	1.5
Contract Ref:	Start:	11.0	1.18	Groun	d Level (m):	National Grid Co-ordinate:	Sheet:			
764393	End:	11.0	1.18		6.55	E:333416.3 N:392560.1		1	of	4
Samples and In-situ Tests	3	ter	Kfill					Depth	Ma	ateria

<u>_</u>	Type Results	Wate Backfi	Description of Strata	(Thick	Graphi
Depth No.	I ES	M Ba	MADE GROUND: Reinforced CONCRETE with subrounded to subangular fine to coarse gravel sized clasts of mixed lithologies Metal bar found in pit, appears to used as shuttering for some concrete present on east edge of pit. MADE GROUND: Coarse gravel sized angular layer of bitumen. Strong ofour of 'tar'. MADE GROUND: Orangish reddish brown SAND and GRAVEL. Gravel is subangular to subrounded fine to coarse of sandstone. Sand is fine to coarse. Trial pit terminated at 2.20m depth.	ness) - 0.15 - 0.35 - 0.35 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	Legen



GINT_LIBRARY V8 06.GLB LibVersion: v8_06_018 PrjVersion: v8_06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8_06. Structural Solis Ltd, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soli



Contract:				Client:			Trial Pit:			
Project E				В	Buro Happold		TF	PSS	31.5	
Contract Ref:	Start:	11.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	11.01.18		6.55		E:333416.3 N:392560.1		2	of	4

Pit facing northward





Pit facing southward

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PriVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:10 | AJ4 | Used:

Method Machine dug **Plant** Used:

13 Ton Tracked Excavator

Logged


Checked **GGoldthorpe**





Contract:				Client:	Trial Pit:					
Project E				E	Buro Happold		TF	PSS	31.5	
Contract Ref:	Start:	11.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	11.01.18		6.55		E:333416.3 N:392560.1		3	of	4

Eastern face





Western face

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:11 | AJ4 |

Method Used:

Machine dug

Plant Used

Used: 13 Ton Tracked Excavator

Logged By:

GGoldthorpe Che By:

Checked





Contract:				Client:			Trial Pit:			
Project E				E	Buro Happold		TF	255	31.5	
Contract Ref:	Start:	11.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	11.01.18		6.55		E:333416.3 N:392560.1		4	of	4

Spoil





Steel from eastern face of pit

Method Used:

Machine dug

Plant Used:

13 Ton Tracked Excavator

Logged

Ву:


Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:11 | AJ4 |

GGoldthorpe






TRIAL PIT LOG

Contract:				Client:		Trial P	it:		
Project	Blue				Buro Happold		TP	SS2	.1
Contract Ref:	Start:	12.0	1.18	Ground Level (m):	National Grid Co-ordinate:	Sheet:			
764393	End:	12.0	1.18	6.66	E:333360.9 N:392418.2		1	of 2	2
Samples and In-situ Te	sts	e	■				Depth	Mate	rial

	Samp	ies a	ina in-si	lu resis	ate	Backfil	Description of Strata	/Thick	Graphic
	Depth	No	Туре	Results	Wate	Вас	Description of Strata	ness)	Legend
-							MADE GROUND: Black tarmacadam containing clasts of mixed lithologies, fine gravel in size.	0.05 0.15	
ŀ							MADE GROUND: Dark grey rectangular to square granite cobbles making a floor (0.10m x 1.0m x 1.0m)	-(0.30)	
404 -							MADE GROUND: Dark grey to black CONCRETE with subrounded fine to medium sized gravel clasts of mixed lithologies. Some brick.	0.45	
PrjVersion: v8_06 - Core+Full Castleford SI - 008 Log TRIAL PIT LOG - A4P 764399 - PROJECT BLUE GPJ - v8_06 otteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, 31/05/18 - 15:44 AJ4					1		\text{Tirial pit terminated at 2.30m depth.} \[\text{Tirial pit terminated at 2.30m depth.} \] \[\text{Tirial pit terminated at 2.30m depth.} \] \[\text{Tirial pit terminated at 2.30m depth.} \]	- (1.85) - (1.85) - (2.30) - (1.85)	





Contract:				Client:			Trial Pit:					
Project E	Blue				E	Buro Happold		TF	PSS	2.1		
Contract Ref:	Start:	12.01.18	Ground	d Level (m):		National Grid Co-ordinate:	Sheet:					
764393	End:	12.01.18		6.66		E:333360.9 N:392418.2		2	of	2		

Excavated foundation and possible pile cap





Method Used:

Machine dug

Plant Used:


13 Ton Tracked Excavator

Logged

GGoldthorpe

Checked








TRIAL PIT LOG

-										
Contract:				С	Client:		Trial P	it:		
Project E	Blue					Buro Happold		TP:	SS	2.2
Contract Ref:	Start:	15.0	1.18	Ground	Level (m):	National Grid Co-ordinate:	Sheet:			
764393	End:	15.0	1.18		6.81	E:333377.4 N:392405.2		1	of	4
Samples and In-situ Tests	3	- in	I≣					Depth	Ma	ateria

	Samples and In-situ Tests Depth No Type Results			tu Tests	ater	X III	Description of Strate	Depth	Material Graphic
	Depth	No	Туре	Results	×	Вас	•	ness)	Legend
rjVerson: v8. 06 - Core+Full Castleford SI - 008 Log TRIAL PIT LOG - A4P 764393 - PROJECT BLUE.GPJ - v8. 06. Itteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk, 31/05/18 - 15:45 AJ4				I	Water	Backfill	MADE GROUND: Light grey (black on fresh surface) TARMACADAM with subangular to angular fine to medium gravel of mixed lithologies. MADE GROUND: Light grey CONCRETE containing cobble to coarse gravel sized clasts of mixed lithologies, mostley granite. MADE GROUND: Orangish reddish brown sandy gravelly CLAY. Gravel is subrounded of sandstone. Sand is fine to coarse overlaying in places retangular blacks of granite (30x10x15). Trial pit terminated at 2.00m depth re-empting water ingress and instability.	(Thick	Graphic



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PriVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE. GPJ - v8 06. Structural Solis Ltd, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis



Contract:					Client:					
Project Blue						TF	255	32.2		
Contract Ref:	Start: 15.01.18 Ground		d Level (m):	Sheet:						
764393	End:	15.01.18		6.81		E:333377.4 N:392405.2		2	of	4

Northern face





Southern face

Method Used:

Machine dug

Plant

Used: 13 Ton Tracked Excavator Logged

Ву:

Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:45 | AJ4 |

GGoldthorpe



Contract:					Client:						
Project Blue				Buro Happold				TF	PSS	32.2	2
Contract Ref:			d Level (m):		National Grid Co-ordinate:	Sheet:					
764393	End:	15.01.18		6.81		E:333377.4 N:392405.2		3	of	4	

Eastern face





Western face

Method Used:

Machine dug

Plant Used:

Logged

Checked Ву:

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:46 | AJ4 |

13 Ton Tracked Excavator

GGoldthorpe



Contract:						Client:						
Project E	Project Blue				Buro Happold					32 .	2	
Contract Ref:	Start: 15.01.18 Ground		l Level (m):		National Grid Co-ordinate:	Sheet:						
764393	End:	15.01.18		6.81		E:333377.4 N:392405.2		4	of	4		

Spoil





Cobbles spoil

Method Used:

Machine dug

Plant Used:

sed: 13 Ton Tracked Excavator

Logged By:

GGoldthorpe

Checked By:

PMR




GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:46 | AJ4 |



TRIAL PIT LOG

Contract:					Trial Pi	it:		
Projec	t Blue			Buro Happold		TP	SS2	.3
Contract Ref: Start:		16.01.18	Ground Level (m):	National Grid Co-ordinate:	Sheet:			
		16.01.18	6.80	E:333356.2 N:392409.8		1	of 4	4
Samples and In city To	octo					Donth	Mate	rial

	Samp	les a	nd In-si	tu Tests	ter	量		Depth	Material
	Depth	No	Туре	Results	Water	Backfill	Description of Strata	(Thick ness)	Graphic Legend
1 + 52 54 - 5	0.30-1.00	1	В				MADE GROUND: Grey to black TARMACADAM with clasts of subrounded fine to medium gravel of mixed lithologies. MADE GROUND: Light grey CONCRETE containing subangular to rounded fine to coarse gravel of mixed lithologies. MADE GROUND: Light grey CONCRETE supporting brick wall of warehouse. Likely a foundation (only on western face, against warehouse wall- see trial pit sketches/projections).	0.05	
ieries, Pouely Sueet, Casueloid, West Tonsillie, WT 10 11WJ. 1et. 019/17-502.259; VAS. U19/17-502.259; Web. WWW.Solis.co.uk, Effall: ask@solis.co.uk, 15/1/09/10.	1.00-2.00	2	В				MADE GROUND: Orangish reddish brown cobbly SAND and GRAVEL. Gravel is subrounded to subangular fine to coarse of sandstone. Sand is fine to coarse. Low to medium cobble content, subrounded to subangular of sandstone and red brick. Trial pit terminated at 2.00m depth due to client inspection having not found piles.	-(1.20)	



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 1008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, | 31/05/18 - 15:46 | AJ4 |



Contract:					Client:					
Project Blue				Buro Happold				TP	SS	32.3
Contract Ref:			d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	16.01.18		6.80		E:333356.2 N:392409.8		2	of	4

Northern face





Eastern face

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:46 | AJ4 |

Method Used:

Machine dug

| Pla | Us

Plant Used: 13 Ton Tracked Excavator

tor B

Logged By: **GGoldthorpe**

Checked By:





Contract:					Client:					
Project Blue						TF	988	32.3		
Contract Ref:			d Level (m):	Sheet:						
764393	End:	16.01.18		6.80		E:333356.2 N:392409.8		3	of	4

Western face





Spoil

Method Used:

Machine dug

Plant Used:

ed: 13 Ton Tracked Excavator

Logged By:

GGoldthorpe

Checked By: PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:47 | AJ4 |


Ta.



Contract:							Trial Pit:			
Project Blue				Buro Happold				TF	PSS	2.3
Contract Ref:			d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	16.01.18		6.80		E:333356.2 N:392409.8		4	of	4

Concrete and tarmac spoil





Structural Soils Ltd, Branch C

Method Used:

Machine dug


Plant Used:

sed: 13 Ton Tracked Excavator

Logged

gged GGoldthorpe Checked By:








TRIAL PIT LOG

Contract:				Client:			Trial Pit:				
Project Blue					Е	Buro Happold		TI	289	32.4	
Contract Ref: Start: 17.01.18 Gr		Ground	d Level (m):		National Grid Co-ordinate:	Sheet:					
764393	End:	17.01.18		6.81		E:333368.3 N:392407.0		1	of	4	

Samples and In-situ Tests	Depth	
Samples and In-situ Tests Depth No Type Results Description of Strata	(Thick ness)	
Depth No Type Results MADE GROUND: Light grey to black TARMM (clasts of subangular to subrounded fine to coarse gravel of the first of subangular to subrounded fine to coarse gravel of the first of subangular to subrounded fine to coarse gravel of the first of subangular to subrounded fine to coarse gravel of the first of subangular to subrounded fine to coarse gravel of the first of subangular to subrounded fine to coarse gravel of the first of the first of the first of subangular to subrounded fine to coarse gravel of the first	ACADAM containing jum gravel of mixed ontaining clasts of mixed lithologies. esent with draininge electing. AND and GRAVEL. subrounded fine to one block protruding concrete. The block ing. (1.50)	Legend



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PrjVersion: v8 06 - Core+Full Castleford SI - 1008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Soils Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email: ask@soils.co.uk, | 31/05/18 - 15:47 | AJ4 |



Contract:					Client:						
Project Blue					E	Buro Happold		TF	PSS	32.	1
Contract Ref:	•		d Level (m):		National Grid Co-ordinate:	Sheet:					
764393	End:	17.01.18		6.81		E:333368.3 N:392407.0		2	of	4	

Northern face





Southern face (brickwork and drainage above)

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:48 | AJ4 |

Method Used:

Machine dug

Plant Used:

13 Ton Tracked Excavator

Logged

GGoldthorpe

Checked Ву:



Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold		TF	PSS	32. 4
Contract Ref:	Start:	17.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	17.01.18		6.81		E:333368.3 N:392407.0		3	of	4

Drainage on top of southern face





Eastern face (with sandstone block present, block excavated during trial pitting)

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:48 | AJ4 |

Method Used:

Machine dug

Plant

Used: 13 Ton Tracked Excavator Logged

GGoldthorpe

Checked Ву:





Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold		TP	PSS	2.4
Contract Ref:	Start:	17.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	17.01.18		6.81		E:333368.3 N:392407.0		4	of	4

Western face





Spoil

Method Used:

Machine dug

Plant Used:

13 Ton Tracked Excavator

Logged


GGoldthorpe

Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:48 | AJ4 |






TRIAL PIT LOG

Contract:				Client:		Trial Pit:			
Project E	Blue				Buro Happold		Т	PSS	32.5
Contract Ref:	Start:	18.01.18	Grour	nd Level (m):	National Grid Co-ordinate:	Sheet:			
764393	End:	18.01.18		6.75	E:333354.7 N:392414.8		1	of	4

Samp	oles a	and In-sit	tu Tests	Water	Backfill	Description of Strata				
Depth	No	Туре	Results	Š	Ba	·	(Thick ness)	Graph Legen		
Plan (Not to 00.2) Bearing — Method Used:						MADE GROUND: Light grey to black TARMACADAM containing clasts of subrounded fine to medium gravel of mixed lithologies. MADE GROUND: Light grey CONCRETE containing clasts of subrangular to subrounded fine to coarse gravel of mixed lithologies. MADE GROUND: Light grey granite COBBLES (0.10x0.15x0.15) MADE GROUND: Orangish reddish brown SAND and GRAVEL. Sand is fine to coarse. Gravel is subrounded to subangular fine to coarse of sandstone. at 0.95m, In western face of pit, a concrete foundation supporting warehouse wall and pile cap. Cap is 1.00m wide (see trial pit sketches/projections for details of structures). Beam foundation has corregated appearance- presumed corregated iron used as shuttering. Trial pit terminated at 1.50m depth.	- (1.15) - 1.50			
Plan (Not to	Sool	ه)			1	General Remarks		-		
i lali (NOLIO	oual	•		1. Location scanned with CAT and Genny and GPR prior to excavation.						
00.5 Description of the second		5.50	342°	 2. Trial pit remained dry and stable during excavation. 3. See trial pit sketches/projections for details on structures in pit. 4. On completion, borehole backfilled with arisings. 						
) Nother-	Madia d			All dimensions in metres Scale: 1:25						
Method Used:	Mad	chine d	lug Plan		3 Ton	Tracked Excavator By: GGoldthorpe Checked By:	MR	AG		





Contract:				Client:			Trial Pit:				
Project E	Blue				E	Buro Happold		TF	25	32	.5
Contract Ref:	Start:	18.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:				
764393	End:	18.01.18		6.75		E:333354.7 N:392414.8		2	of	4	ļ.

Northern face





Western face, showing foundation and possible pile cap

GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PriVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:49 | AJ4 |

Method Used:

Machine dug

Plant Used:

ed: 13 Ton Tracked Excavator

Logged By:

GGoldthorpe Chee


Checked 6

PMR AGS



Contract:				Client:			Trial Pit:			
Project E	Blue				E	Buro Happold		TF	25	32.5
Contract Ref:	Start:	18.01.18	Groun	d Level (m):		National Grid Co-ordinate:	Sheet:			
764393	End:	18.01.18		6.75		E:333354.7 N:392414.8		3	of	4

Southern face





Eastern face

Method Used:

Machine dug

Plant Used:

13 Ton Tracked Excavator

Logged

GGoldthorpe

Checked

PMR



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PriVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 06.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:49 | AJ4 |



Contract:				Client:			Trial Pit:				
Project E	Blue				E	Buro Happold		TF	25	32 .	5
Contract Ref:	Start:	18.01.18	Ground	l Level (m):	el (m): National Grid Co-ordinate:						
764393	End:	18.01.18		6.75		E:333354.7 N:392414.8		4	of	4	

Spoil



GINT_LIBRARY V8 06.GLB LibVersion: v8 06 018 PijVersion: v8 06 - Core+Full Castleford SI - 008 | Log TRIAL PIT LOG - A4P | 764393 - PROJECT BLUE.GPJ - v8 08.
Structural Solis Lid, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.solis.co.uk, Email: ask@solis.co.uk. | 31/05/18 - 15:49 | AJ4 |

Method Used:

Machine dug

Plant Used:


13 Ton Tracked Excavator

Logged

GGoldthorpe

Checked







SUMMARY TABLE OF GROUND LEVELS AND CO-ORDINATES AT EXPLORATORY HOLE LOCATIONS

Contract:		Client:		Contract Ref:
Pı	oject Blue	В	uro Happold	764393
Exploratory	Grid Co-0	Ordinates	0	
Position ID	Eastings (m)	Northings (m)	Ground Level (m)	Hole Type Codes
BH1	333601.4	392565.4	6.93	RO
BH101	333259.5	392529.6	6.55	CC+IP+DS+RC
BH102	333278.4	392411.3	6.73	CC+IP+DS+RC
BH102A	333278.3	392411.8	6.72	RO
BH103	333298.3	392491.8	-3.16	DS+RC
BH104	333338.4	392535.5	-1.88	DS+RC
BH105	333327.2	392443.9	-2.86	DS+RC
BH106	333375.7	392522.9	-2.62	DS+RC
BH107	333381.5	392452.6	-2.88	DS+RC
BH108	333401.2	392408.7	6.81	CC+IP+DS+RC
BH108A	333402.2	392408.9	6.80	RO
BH109	333457.1	392569.5	6.63	IP+DS+RC+DS+RC
BH110	333458.7	392487.8	-2.65	DS+RC
BH111	333528.5	392567.7	6.70	CC+IP+DS+RC
BH112	333549.3	392515.5	-2.45	DS+RC
BH113	333544.3	392470.8	-2.68	DS
BH113A	333553.0	392472.0	-2.98	DS+RC
BH114	333502.4	392415.2	6.76	CC+IP+DS+RC
OH101	333368.2	392383.3	6.82	RO
OH102	333393.5	392565.0	6.71	RO
OH103	333613.1	392465.2	6.81	RO
P101	333391.4	392550.0	6.46	TP
P101A	333395.0	392551.7	6.44	RO+RC
P101B	333394.4	392551.0	6.50	RO
P101C	333390.9	392550.0	6.46	RO+RC
P102	333534.9	392557.1	6.62	TP
P102.1	333532.6	392556.9	6.62	TP
P102A	333537.6	392556.6	6.62	RO
P103A	333405.0	392419.9	6.67	RO+RC
P103B	333403.9	392423.3	6.60	RO+RC
P104A	333502.3	392423.8	6.63	RO+RC
P104B	333502.2	392426.7	6.61	RC

Notes:

Hole type codes: CC = Concrete core, IP = Inspection pit, DS = Dynamic sampling, RC = Rotary Cored, RO = Rotary open hole, TP = Trial Pit/trench





SUMMARY TABLE OF GROUND LEVELS AND CO-ORDINATES AT EXPLORATORY HOLE LOCATIONS

Contract:		Client:		Contract Ref:				
P	roject Blue	В	Buro Happold					
Exploratory	Grid Co-0	Ordinates						
Position ID	Eastings (m)	Northings (m)	Ground Level (m)	Hole Type Codes				
P105	333289.2	392474.4	6.65	TP				
P105A	333289.1	392473.2	6.65	RO+RC				
P105B	333288.4	392473.1	6.66	RO				
P105C	333289.8	392473.2	6.66	RO				
P106	333285.9	392521.7	6.67	TP				
P106A	333285.7	392521.6	6.63	RO+RC				
P106B	333286.6	392521.6	6.61	RO				
P106C	333286.2	392521.7	6.64	RO+RC				
P106D	333285.0	392521.7	6.70	RO				
PAC01A	333300.9	392534.4						
PAC01B	333314.0	392516.2						
PAC02A	333321.0	392428.1						
PAC02B	333313.7	392446.7						
PAC03A	333390.6	392452.1						
PAC03B	333393.9	392472.7						
PAC04A	333420.6	392542.2						
PAC04B	333436.3	392543.3						
PAC05A	333416.6	392488.7						
PAC05B	333456.3	392502.2						
PAC06A	333469.8	392458.0						
PAC06B	333495.1	392453.6						
PAC07A	333591.3	392527.2						
PAC07B	333573.3	392537.8						
PAC08A	333548.3	392449.7						
PAC08B	333555.4	392473.5						
TPSS1.1	333393.0	392568.2	6.56	TP				
TPSS1.2	333406.0	392568.3	6.57	TP				
TPSS1.3	333396.4	392554.7	6.58	TP				
TPSS1.4	333387.4	392559.5	6.54	TP				
TPSS1.5	333416.3	392560.1	6.55	TP				
TPSS2.1	333360.9	392418.2	6.66	TP				
TPSS2.2	333377.4	392405.2	6.81	TP				

Notes:

Hole type codes: CC = Concrete core, IP = Inspection pit, DS = Dynamic sampling, RC = Rotary Cored, RO = Rotary open hole, TP = Trial Pit/trench





SUMMARY TABLE OF GROUND LEVELS AND CO-ORDINATES AT EXPLORATORY HOLE LOCATIONS

Contract:		Client:			Contract Ref:		
P	roject Blue	E	Buro Happold	pold 764			
Exploratory	Grid Co-O	rdinates	Ground Level		ala Tura Cadaa		
Position ID	Eastings (m)	Northings (m)	(m)	H	ole Type Codes		
TPSS2.3	333356.2	392409.8	6.80	TP			
TPSS2.4	333368.3	392407.0	6.81	TP			
TPSS2.5	333354.7	392414.8	6.75	TP			

Notes:

Hole type codes: CC = Concrete core, IP = Inspection pit, DS = Dynamic sampling, RC = Rotary Cored, RO = Rotary open hole, TP = Trial Pit/trench



SUMMARY OF INSTALLATION AND PIEZOMETER CHARACTERISTICS

Remarks									
Targetted Ground		I	ŀ	I	-			I	1
Pipe Internal Diameter (mm)	50	19	35	19	35	20	50	50	50
Slotted Pipe Base (m)	3.50	ŀ	5.00	ŀ	14.50	5.00	3.00	4.00	5.50
Slotted Pipe Top (m)	09:0	l	1.00	l	12.50	4.50	09:0	0.50	0.50
Response Response Zone Zone Top Base (m) (m)	3.50	5.50	5.50	15.00	15.00	5.00	3.00	4.50	5.50
Response Zone Top (m)	09:0	0.50	1.00	12.00	12.00	0.50	0.50	0.50	0.50
Piezo meter Depth (m)	-	4.50	ŀ	14.00			-	1	
Length of Pipe (m)	3.50	4.50	5.00	14.00	14.50	5.00	3.00	4.00	5.50
Ground	6.55	6.73	6.72	6.81	6.80	6.76	6.82	6.71	6.81
Pipe Top Level (m)		ŀ	ŀ	ŀ				I	1
Cover		!	!	ŀ				l	1
Pipe Caption	-	ŀ	ŀ	ŀ			-	1	1
Exploratory Position ID	BH101	BH102	BH102A	BH108	BH108A	BH114	OH101	OH102	OH103

Contract Ref:	764393	Page: 1 of
Date	13.04.18	
Compiled By	AJONES	Project Blue
Compi	4	Contract:
S IIOS IVAI ITALIA	The Potteries	Pottery Street Castleford Yorkshire WF10 1NJ

GINT_LIBRARY_V8_06.GLB: G-SUMMARY OF INSTALLATIONS - A4L: 764393 - PROJECT BLUE.GPJ: 13/04/18 15:38 : AJ4:



APPENDIX C - IN-SITU TESTING

- (i) Standard Penetration Test (SPT) Summary Sheet
- (ii) SPT N value versus Elevation Plot
- (iii) Permeability Test Results