

Appendix B. Survey Viewpoint Location Drawings

B.1 Drawing No 317415-EIA-001

B.2 Drawing No 317415-EIA-001

Notes

LIGHTING SYMBOLS ARE INDICATIVE AND ARE NOT TO SCALE.
DO NOT SCALE FROM THIS DRAWING.

Key to symbols

- Site Boundary
- Existing Street Lighting Column
- Survey Viewpoint location with reference number
- Photo location with reference number
- Residential properties demolished pre site survey
- Residential properties to be demolished post site survey

Photo Locations	
1	Walton Breck Road (Figure 4.1 and 4.2 in report)
2	Gillman Street (Figure 4.3 and 4.4 in report)
3	Gillman Street towards stadium (Figure 4.5 and 4.6 in report)
4	Baltic Street (Figure 4.7 and 4.8 in report)
5	Alroy Road (Figure 4.9 and 4.10 in report)
6	Rockfield Road (Figure 4.11 and 4.12 in report)
7	Anfield Road and footway to Stanley park (Figure 4.13 and 4.14 in report)
8	Stanley Park - Location 1
9	Stanley Park - Location 2 (Figure 4.16 and 4.17 in report)
10	Anfield Road (Figure 4.18 and 4.19 in report)
11	Stanley Park - Location 3
12	Skerne Road (Figure 4.20 and 4.21 in report)
13	North West Car Park (Figure 4.22 in report)
14	North West Car Park (Figure 4.23 in report)

Reference drawings

Rev	Date	Drawn	Description	Chk'd	App'd



1st Floor
Esplanade, 89-91 Thorpe Road
Norwich, NR1 1UA
United Kingdom
T +44 (0)1603 286780
F +44 (0)1603 619665
W www.mottmac.com


Client

LFC EIA - Lighting Assessment
Survey Viewpoint Locations
Drawing 1 of 2

Designed	Ian Hearnsum	U/H	Eng check	Jamie Mckay	JMM
Drawn	Ian Hearnsum	U/H	Coordination	Hattie Jenkins	
Dwg check	Jamie Mckay	JMM	Approved	A. Lawrence	
Scale at A1	1:500	PRE	Status	Rev	P1

Drawing Number

317415 - EIA - 001



This document should not be relied on or used in circumstances other than those for which it was originally prepared and for which Mott MacDonald has been commissioned. Mott MacDonald accepts no responsibility for its use by any other person than the person by whom it was commissioned.

Notes

LIGHTING SYMBOLS ARE INDICATIVE AND ARE NOT TO SCALE.
DO NOT SCALE FROM THIS DRAWING.

Key to symbols

- Site Boundary
- Existing Street Lighting Column
- Survey Viewpoint Location with reference number
- Photo location with reference number
- Residential properties demolished pre site survey
- Residential properties to be demolished post site survey

Photo Locations	
1	Walton Breck Road (Figure 4.1 and 4.2 in report)
2	Gillman Street (Figure 4.3 and 4.4 in report)
3	Gillman Street towards stadium (Figure 4.5 and 4.6 in report)
4	Baltic Street (Figure 4.7 and 4.8 in report)
5	Alroy Road (Figure 4.9 and 4.10 in report)
6	Rockfield Road (Figure 4.11 and 4.12 in report)
7	Anfield Road and footway to stanley park (Figure 4.13 and 4.14 in report)
8	Stanley Park - Location 1
9	Stanley Park - Location 2 (Figure 4.16 and 4.17 in report)
10	Anfield Road (Figure 4.18 and 4.19 in report)
11	Stanley Park - Location 3
12	Skerries Road (Figure 4.20 and 4.21 in report)
13	North West Car Park (Figure 4.22 in report)
14	North West Car Park (Figure 4.23 in report)

Reference drawings


Rev	Date	Drawn	Description	Chk'd	App'd



1st Floor
East Wing, 69-75 Thorpe Road
Northwich, Cheshire, WA8 7LN
United Kingdom
T +44 (0)1603 298760
F +44 (0)1603 619365
W www.mottmac.com

Client

Title					
LFC EIA - Lighting Assessment					
Survey Viewpoint Locations					
Drawing 2 of 2					
Designed	Ian Heasum	U/H	Eng check	Jamie Mckay	JMM
Drawn	Ian Heasum	U/H	Coordination	Hattie Jenkins	
Dwg check	Jamie Mckay	JMM	Approved	A Lawrence	
Scale at A1					
1:500	PRE	Status	Rev	P1	
Drawing Number					
317415 - EIA - 002					



Appendix C. Photos Sheets

C.1 Photo sheets

Liverpool Football Club Lighting Assessment. Appendix C.1. – Photo Sheets.

Daytime Weather conditions



Night-time Weather Conditions

