


## TRIAL PIT LOG

Contract: <b>Bramley Moore Dock Wall</b>			Client: <b>Everton FC</b>	Trial Pit: <b>TP02</b>
Contract Ref: <b>764954</b>	Start: <b>31.07.19</b> End: <b>31.07.19</b>	Ground Level (m AOD): <b>7.07</b>	National Grid Co-ordinate: <b>E:333657.8 N:392502.4</b>	Sheet: <b>4 of 7</b>


TP02 Face A 03



TP02 Face A 04

Method Used: <b>Machine dug</b>	Plant Used: <b>JCB-3CX Backhoe Excavator</b>	Logged By: <b>IHayes</b>	Checked By: <b>M6</b>	
---------------------------------	--	--------------------------	-----------------------	--





## TRIAL PIT LOG

Contract: <b>Bramley Moore Dock Wall</b>		Client: <b>Everton FC</b>		Trial Pit: <b>TP02</b>
Contract Ref: <b>764954</b>	Start: <b>31.07.19</b> End: <b>31.07.19</b>	Ground Level (m AOD): <b>7.07</b>	National Grid Co-ordinate: <b>E:333657.8 N:392502.4</b>	Sheet: <b>5 of 7</b>


TP02 Face B



TP02 Face C

Method Used: <b>Machine dug</b>	Plant Used: <b>JCB-3CX Backhoe Excavator</b>	Logged By: <b>IHayes</b>	Checked By: <b>M6</b>	
------------------------------------	---	-----------------------------	--------------------------	--





## TRIAL PIT LOG

Contract: <b>Bramley Moore Dock Wall</b>		Client: <b>Everton FC</b>		Trial Pit: <b>TP02</b>
Contract Ref: <b>764954</b>	Start: <b>31.07.19</b> End: <b>31.07.19</b>	Ground Level (m AOD): <b>7.07</b>	National Grid Co-ordinate: <b>E:333657.8 N:392502.4</b>	Sheet: <b>6 of 7</b>

TP02 Face D



TP02 Pit Bottom

Method Used: <b>Machine dug</b>	Plant Used: <b>JCB-3CX Backhoe Excavator</b>	Logged By: <b>IHayes</b>	Checked By: <b>M6</b>	
------------------------------------	---	-----------------------------	--------------------------	--