PLATE 1 – TP101



PLATE 2 – TP 102



July 2014 44808p1r3

PLATE 3 – TP108 LANDFILL WASTE



PLATE 4 – TP116



PLATE 5 – WS103



PLATE 6 – WS106



PLATE 7 – WS113



PLATE 8 – WS116



July 2014 44808p1r3

PLATE 9: LOOKING WEST FROM GRANGE LANE, VISIBLE ARE THE REMAINS OF THE SCHOOL BUILDINGS AND THE RAISED LANDFILLED AREA IN THE BACKGROUND



PLATE 10: LOOKING EAST FROM THE RAISED LANDFILL AREA TOWARDS GRANGE LANE. VISIBLE ARE THE REMAINING SCHOOL FOUNDATIONS.



PLATE 11: LOOKING SOUTH EAST FROM THE RAISED LANDFILL AREA TOWARDS THE FORMER TENNIS COURTS. JUST VISIBLE ARE THE JAPANESE KNOTWEED STANDS



PLATE 12: THE EXISTING RETAINING WALL ON THE TENNIS COURTS RETAINING THE LANDFILL MATERIAL.



APPENDIX V

HISTORICAL MAPS







