



Tree trees Close to Building.
G 2. Lifting flags and causing very Bad
Trip Hazard. See photos



Car Park



○ TI Willows

Fell
To Ground
Level

Fallen Branch.
Big tear in top.
Not in good

Condition.

See
Photos



Car Park

Car Park

Lower Bank Rd.