




16/12/83

26/8/16.

- ③ Over hanging branches of DATE tree, over a public pavement on Vale Road.

⑦ This is a large branch which sometimes hits the road and is carrying a lot of weight we think this is causing the tree to grow closer against the wall.

Beech Tree

⑤

Top of wall has angled bricks along the top layer. This is being pushed out due to pressure.

Previous work done to wall

⑤

VALE ROAD SIDE OF WALL

16T/2183

26/8/16.